Oil Field Environmental Incident Summary

Responsible Party: CONTINENTAL RESOURCES, INC. **Well Operator:** CONTINENTAL RESOURCES, INC.

Well Name: NORWAY 1-5H

Field Name: FANCY BUTTES Well File #: 19380

Date Incident:6/4/2015Time Incident:07:35Facility ID Number:County:MCKENZIETwp:150Rng:96Sec:5Qtr:

Location Description:

Submitted By: Todd Senescall Received By:

Contact Person: Shane Teigen

PO BOX 268870

OKLAHOMA CITY, OK 73126

General Land Use: Cultivated Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: No Reported to NRC: No

SpilledUnitsRecoveredUnitsFollowupUnits5Gallons0gallons

Brine Other

Oil

Description of Other Released Contaminant:

Inspected: Written Report Received: 12/7/2016 Clean Up Concluded: 6/4/2015

Risk Evaluation:

fire

Areal Extent:

Approximately 0.1 acres of cultivated field was lightly misted.

Potential Environmental Impacts:

soil, vegetation

Action Taken or Planned:

Left voicemail with landowner. Misted oil will be left to natural attenuation with landowner permission. Soil sampling conducted. Dump valve was reknitted.

Wastes Disposal Location: N/A

Agencies Involved: Joyce Kohut, NDIC Inspector (phone message)

Bill Suess, NDDH (phone message)

Updates

Date: 6/5/2015 Status: Reviewed - Follow-up Required Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release impacted areas off location. Followup is required.

Date: 6/9/2015 Status: Awaiting Documentation Author: Washek, Sandi

Updated Oil Volume: 5.00 gallons

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on site at 2:40 p.m. Sunny 77 F, wind NW at 15-20 mph. Impacted area of oil spray is located west of the flare pit. Area is about 10 feet long by 8 feet wide. Impacted the wheat field that is planted. Wheat is in the 5-leaf stage. Most of the spray is located on the pad and along the fence line. Will require documentation for natural attenuation of the oil. No water was impacted.

Date: 7/16/2015 Status: Inspection Author: Washek, Sandi

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Company rep provided sampling results and map for area impacted. In addition, received a response back from the landowner pertaining to cleanup. Landowner wants to wait for any additional cleanup (soil removal) to see what type of impact is occurring to his crop. Department will do additional follow-up inspection of the area at the end of August/September.

Date: 9/3/2015 Status: Inspection Author: Washek, Sandi

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on-site at 12:17 pm 81 degrees sunny, wind out of the SW at 10 mile/hr. The impacted field is located to the west of the pad. The field has been harvested and no staining of the soil could be found. No additional follow-up needed.

Date: 3/10/2016 Status: Correspondence Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Bill Suess sent a No Further Action letter dated March 10, 2016.